

市售「電風扇」商品檢測結果不符合規定商品照片

項次	不符合情形	商品照片
8	馬達啟動電容器之規格為 $3\mu\text{F}$ 、 85°C ，與原登錄技術文件為 $3.5\mu\text{F}$ 、 70°C 不符。	 A photograph of a black and orange electric fan. The fan has a circular grille with a black mesh and an orange border. The central motor housing is orange with a white checkered logo. The fan is mounted on a black stand with a circular base. The background is a plain, light-colored wall.